







Ax1




Bx1




Cx1



Dx2



Ex2



Fx10



M4x6mm

Gx4



M4x6mm

Hx14




Ix1



Jx3




1




	Fx2
	Hx2

2




	Fx3
	Hx3

3



	Fx5
	Hx9
	Gx4

4



	Jx3
---	-----