

CATAS S.p.A. Iscr. Reg. Imprese Udine nr. iscr. C.F. 01818850305 Reg. Impr. UD 20663 P. IVA: 01818850305 C.Soc. € 1.003.650,00 i.v.

Sede: Via Antica, 24/3 33048 S. Giovanni al Nat. UD Via Braille, 5 Tel. 0432.747211 r.a. Fax 0432.747250 http://www.catas.com lab@catas.com

Filiale: 20851 Lissone MB Tel. 039.464567 Fax 039.464565 lissone@catas.com

**UL.MELIORACYJNA 6** 

57-200 ZABKOWICE SLASKIE ()

ALDA S.A.

PL - POLAND

Date received: 22/12/15

Date of issue: 08/01/16

Report consists of 1 test report.

Defects before testing: None

Sample name: 90342263 RACKEL pedal bin 30 I stainlless steel

70324464 RACKEL pedal bin 30 I stainlless steel

### **SAMPLE N° 207066**

Overall dimensions: 360 x 300 x 640 (h) mm

#### List performed tests:

1. Durability of flaps ISO 7170:2005, clause 7.3.2



This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

> anaging Director Andrea Giavon

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer.



CATAS S.p.A. Iscr. Reg. Imprese Udine nr. iscr. C.F. 01818850305 Reg. Impr. UD 20663 P. IVA: 01818850305 C.Soc. € 1.003.650,00 i.v.

Sede: Via Antica, 24/3 33048 S. Giovanni al Nat. UD Via Braille, 5 Tel. 0432.747211 r.a. Fax 0432.747250 http://www.catas.com lab@catas.com

Filiale: 20851 Lissone MB Tel. 039.464567 Fax 039.464565 lissone@catas.com

#### **TEST REPORT**

## 207066 / 1

Date received: 22/12/15 Date of test: 07/01/16 Date of issue: 08/01/16



ALDA S.A. **UL.MELIORACYJNA 6** 57-200 ZABKOWICE SLASKIE PL - POLAND

Sample name: 90342263 RACKEL pedal bin 30 I stainlless steel

70324464 RACKEL pedal bin 30 I stainlless steel

# Durability of flaps ISO 7170:2005, clause 7.3.2

Dimensions: Diam. 290 x 35 mm

Material: Metal

Application point: at the pedal

Tests results:

Number of cycles	Remarks
10000	No defects

Note: as agreed with the customer, the cover of the bin has been opened and closed by pushing and releasing the pedal, for the number of cycles in table above.

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic sianature systems.

anaging Director

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer. pag. 1/1